No: EM.1(10)/83/6470

Dat at: 26-5.57

CIRCULYR .... 202

It has come to notice that some of the floor traps (water seals) used on the DEA works are not according to ISI specification. Instead of proviring the desired water seal and a free throat, the traps used are having a constriction near the outlet which may cause checkages leading to the pressure of dampness. Officers are requested to please ensure that the traps used on the work fully satisfy the ISI specification.

It is also necessary for the engineers to plan the location of the door bends in such a way the inspection door can be opened conveniently and cleaning operation conducted properly. The door bends have special function and this should be well understood. Copies of the circular should be circulated up to the level of Junior Engineers by the Executive Engineers.

(V.S. Murti) P2/5:87 Engineer Member

Copy to: All CCs, All SCs & All ECs.