DELII DEVELOPMENT AUTHORITY

No. Sm1 (10) 80/111932 Dt., the 19th Dec., 1985.

An instance has come to our notice where a 12 ft. long plank placed in the expansion joint was not removed at the time of finishing of the houses and it : came down subsequently causing damage to property and injury to the occupants. This shows total carelessness of the supervisory staff. All the Executive Engineers should examine the various houses in their charge and ensure that any plank which is left behind in the expansion joint is removed right now. If any incident occurs subsequently, the concerned EE will be proceeded against.

> J.K. Varshneya Engineer Member

Copy to:-

All CEs.