

224 ————— 135

DELHI DEVELOPMENT AUTHORITY

No. Sm 1(10)83/2329

Dated 26/2/86

CIRCULAR NO 135

While covering the deep drains the pre-cast RCC slabs are provided at intervals for inspection and cleaning of the drains as and when required. It has been reported that in case of certain drains, either the pre-cast slabs have not been provided or these are not placed in position back after cleaning the drains. These open gaps are hazardous and prone to accidents.

It has also come to notice that in case of sewer lines the man-hole covers are also found removed or missing, and no action is taken to cover these man holes immediately. These open man-holes also can lead to accidents. It is, therefore, necessary that the man-holes are always kept covered with proper covers so that no such mishap takes place.

It is enjoined upon all Engineers to ensure that there should not be any such gap on deep covered drains and no man-hole should be left uncovered in order to avoid any mishap or accident.

The above instructions shall be followed very strictly.

( Om Prakash )  
Director (Works)

1. All Chief Engineers.
2. All Supt. Engineers.
3. All Executive Engineers.

} through concerned  
Chief Engineers

copy to file no Sm 3(11)81