NE .: EM. 1(10) = 52/VOL-1/159

CIRCULAR NO. 528

Test Checking of measurement SUB.

The CPWD vide office Memorendum No. DGW/MAN/38 dt. 19.11.99 has issued a clarification about Test Checking of Measurements which are reproduced as under:-

"Para 7.30 to 7.33.1 of CPWD Manual Vol. II deal with the test checking of measurements by Executive Engineer and Assistant Executive Engineer/Assistant Engineer recorded by their sub-ordinate officers to the extent of specified percentages by each. Doubt has been raised as to whether the specified percentage relates to the number of measurements corded or to the corresponding monetary value of the measurements f work done. It is, hereby, clarified that for the purpose of test check, 'measurements' means the "corresponding monetary value of measurements of work done. This, however, does not apply to "Levels" in which case the test check has got to be based on the number of levels recorded."

The above clarification has been made applicable in D.D.A. also with the approval of E.M.

> DIRECTOR (WORKS) D.D.A.

Copy to:

All CEs. 1. All SEs circulation through their respective CEs. 2. CVO i/c SE(Vic.)-I, SE(Vig.)-II & SE(Vig.)-III, DDA. 3. Project Manager Flyover Project Gr.I & II, D.D.A. MO, DDA. Dir. (Hort.) North & South, Dir. (MM), D.D.A. Director (Works, D.D.A. All EEs circulation through their respective CEs/Mreject Manager (Flyover), D.D.A. All Jt. Dir./Dy. Dir.(Hort.) Circulation through respective Dir.(Hort.) All Dy./Jt. CAS's attached to CEs, FOs to Dir. (Hort.) North & South Diz. (MH), D.D.A. E.B.-I,II,III & IV to E.M., D.D.A. A.C.(Plan) to E.M. File No.EM1(1C) 98/Vol-I/pt.III. y for information to:-

V. C., D.D.A.

F.M., DDA

E.O. 1 to E.M.