

203

123

DELHI DEVELOPMENT AUTHORITY.

NO:EMI(10)83/15028

DATE: 23-12-85

CIRCULAR NO. 123

It has come to notice that in certain contracts rates withheld in the running account bills were less than reductions effected subsequently. This results in undue financial aid to the contractor, besides this can also lead to avoidable litigation subsequently.

It is requested to ensure that part rates paid in running account bills are proportionate to the work done and sufficient amount should be kept withheld for the work yet to be done/defects to be removed. Any lapse in this regard resulting in over payment will be viewed very seriously. The Executive Engineers authorising part payment shall be personally responsible for the correctness of rates.

ENGINEER MEMBER.

D. M.

1. All Chief Engineers.
2. All Substd. Engineers.
3. All Executive Engineers.