DELHI DEVELOPMENT AUTHORITY (EM'S OFFICE)

NO: E: .1 (10)95/ 9503

Dat.cd: 10.5.95

CIRCULAR NO. 456

SUB: NON-PROVISION OF CP ENASS TRAPS AND UNIONS WHERE THE WASTE PIPES OF THE WASH PASINS ARE DIRECTLY DISCHARGING INTO FLOOR TRAPS ETC.

During one of the inspections of DDA works, the CTE had observed that CP Brass traps and unions had been provided in the waste pipe of the wash basins even when the waste pipe was directly discharging into the floor traps. Such a provision had resulted in an avoidable extra expenditure.

In this context, attention of all engineers is invited to the specific provision of Cl-use-18.12.1 of CPWD Specification-1977 Vol.-II which stipulates that CP Brass trap and unions are required to be provided only when the waste pipes are to be embedded in the walls, whereas, no CP Brass trap and unions are to be provided when the waste is discharged through the floor traps.

In view of the above provision of the specifications, it is enjoined upon all engineers to strictly comply with these specifications so that unnecessary expenditure is not incurred in providing CP Brass trap and unions where waste pipes are directly discharging into floor traps. They must also ensure that proper provision is kept in the agreements to incorporate the item of "Deduct for not providing CP Brass trap and unions etc." so that the requisite recoveries could be affected without fail for not providing these fixtures as per the requirement of the site conditions.

It is also simultaneously enjoined upon all engineers to ensure that in all the on going contracts Engineer-in-Charge are given in the enclosed Annexure.

These instructions must be followed scrupulously.

Encl: As above.

て、大フラル

(R.L. HANS) ENGINEER MEMDER

- 1. All Chief Figineers, DDA 1/c CF(QC), CF(D) & CF(Flect.)
- 2. OSD to V.C for kind information of V.C.
- 3: All S.Es, DDA 1/c SEs(QC), SE(D) & SE(Elect.).
 - 4. Director (MM), DDA.
 - 5. Director (Hort.) South & Borth, DDA.
 - 6. All EEs, DDA 1/c EE's (QC), ET(D) & EF's (Elet.)
 - 7. All Dy. of recters (lbet.), DDA.
 - 8. File No. EM15 (3)93/Inspection.

C. E 3.500

Engineer Member D.D.A.

iyir.